


SOLDER TO WEB  
OF SWITCH BLADE



SOLDER TO PCB

GAP THE COPPER. OFFSET ON  
THE OTHER SIDE

OR ← FROM T.O.U.